

compliance with this AD, if any, may be obtained from the New York ACO.

Note 3: Alternative methods of compliance approved in accordance with AD 83-26-05 or AD 86-15-08 (both superseded by this action) are not considered approved as alternative methods of compliance with this AD.

(f) The inspections required by this AD shall be done in accordance with de Havilland Service Bulletin No. 6/438, Revision D, dated March 28, 1986. The modifications required by this AD shall be done in accordance with de Havilland Service Bulletin No. 6/513, dated October 25, 1991. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from de Havilland, Inc., 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5 Canada. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., 7th Floor, suite 700, Washington, DC.

(g) This amendment (39-9415) supersedes AD 83-26-05, Amendment 39-4793, and AD 86-15-08, Amendment 39-5362.

(h) This amendment (39-9415) becomes effective on December 27, 1995.

Issued in Kansas City, Missouri, on October 18, 1995.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-26403 Filed 10-27-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 94-NM-173-AD; Amendment 39-9409; AD 95-22-02]

Airworthiness Directives; Jetstream Model ATP Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to certain Jetstream Model ATP airplanes, that currently requires daily and/or pre-flight cleaning and inspections to detect damaged main landing gear (MLG) wheel bearings and replacement of discrepant parts. That AD was prompted by reports of failure of the MLG wheel bearings. This action requires an additional inspection, in lieu of the pre-flight inspection, for certain airplanes. This action also requires the accomplishment of a terminating modification that eliminates the need for daily and pre-flight inspections. The actions specified by this AD are intended to prevent failure of the MLG wheel bearing, which could

result in detachment of a MLG wheel from the airplane.

DATES: Effective November 29, 1995.

The incorporation by reference of certain publications, as listed in the regulations, is approved by the Director of the Federal Register as of November 29, 1995.

The incorporation by reference of Jetstream Service Bulletin ATP-32-48, Revision 1, dated January 28, 1994, was approved previously by the Director of the Federal Register as of March 15, 1994 (59 FR 9400, February 28, 1994).

ADDRESSES: The service information referenced in this AD may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041-6029. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: William Schroeder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2148; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 94-05-03, amendment 39-8841 (59 FR 9400, February 28, 1994), which is applicable to certain Jetstream Model ATP airplanes, was published in the Federal Register on June 12, 1995 (60 FR 30798). The action proposed to continue to require daily cleaning and daily/pre-flight detailed visual inspections to detect damage (including blistering or flaking of the paint) or discoloration of the wheel hub caps and of the outer side of the inflation valve side hubs on the MLG wheels. The action also proposed to require an additional daily intermediate detailed visual inspection, in lieu of the pre-flight inspection, for certain airplanes. Additionally, the action proposed to require modification of the MLG, which would constitute terminating action for the daily, pre-flight, and daily intermediate inspection requirements.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

After careful review of the available data, including the comment noted

above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 10 airplanes of U.S. registry will be affected by this AD.

The inspections that were previously required by AD 94-05-03, and retained in this AD, take approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the total cost impact of the inspection requirement of this AD on U.S. operators is estimated to be \$1,200, or \$120 per airplane, per inspection cycle.

The inspections that will be added by this AD will take approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the total cost impact of the inspections required by this AD on U.S. operators is estimated to be \$1,200, or \$120 per airplane, per inspection cycle.

It will take approximately 11 work hours per airplane to accomplish the required modifications at an average labor rate of \$60 per work hour. Required parts will be supplied by the manufacturer at no cost to the operators. Based on these figures, the total cost impact of the modification required by this AD on U.S. operators is estimated to be \$6,600, or \$660 per airplane.

The total cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules

Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39–8841 (59 FR 9400, February 28, 1994), and by adding a new airworthiness directive (AD), amendment 39–9409, to read as follows:

95–22–02 Jetstream Aircraft Limited (Formerly British Aerospace Commercial Aircraft Limited): Amendment 39–9409. Docket 94–NM–173–AD. Supersedes AD 94–05–03, Amendment 39–8841.

Applicability: Model ATP airplanes, constructor numbers 2001 through 2063 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent detachment of a main landing gear (MLG) wheel from the airplane, accomplish the following:

(a) For airplanes on which Jetstream Modification 35296A (reference Jetstream Service Bulletin ATP–32–51–35296A) has not been installed: Accomplish paragraphs (a)(1) and (a)(2) of this AD.

(1) Within 24 hours after March 15, 1994 (the effective date of AD 94–05–03,

amendment 39–8841), perform a cleaning and a detailed visual inspection to detect damage (including blistering or flaking of the paint) or discoloration of the wheel hub caps and of the outer side of the inflation valve side hubs on the MLG wheels, in accordance with paragraph 2.(2) of the Accomplishment Instructions of Jetstream Service Bulletin ATP–32–48, Revision 1, dated January 28, 1994; or in accordance with paragraph 2.A.(2) of the Accomplishment Instructions of Jetstream Service Bulletin ATP–32–48, Revision 3, dated July 15, 1994. Thereafter, prior to the first flight of each day, repeat this cleaning and inspection. The cleaning and inspection must be performed by appropriately certificated maintenance personnel as specified in section 43.3 of the Federal Aviation Regulations (14 CFR 43.3). If any damage or discoloration is found during any inspection required by this paragraph, prior to further flight, replace the existing MLG wheel assembly and bearings with a serviceable wheel assembly and bearings, in accordance with the airplane maintenance manual.

(2) Following accomplishment of the initial inspection required by paragraph (a)(1) of this AD, prior to each flight, with the exception of the first flight of each day, perform a pre-flight detailed visual inspection to detect damage (including blistering or flaking of the paint) or heat discoloration of the wheel hub cap and the outer side of each inflation valve side hub on the MLG wheels, in accordance with paragraph 2.A.(3) of the Accomplishment Instructions of Jetstream Service Bulletin ATP–32–48, Revision 1, dated January 28, 1994; or in accordance with paragraph 2.A.(3) of the Accomplishment Instruction of Jetstream Service Bulletin ATP–32–48, Revision 3, dated July 15, 1994. The pre-flight inspections must be performed by appropriately certificated maintenance personnel, as specified in section 43.3. If any damage or discoloration is found during any inspection required by this paragraph, prior to further flight, replace the existing MLG wheel assembly and bearings with a serviceable wheel assembly and bearings, in accordance with the airplane maintenance manual.

(b) For airplanes on which Jetstream Modification 35296A (reference Jetstream Service Bulletin ATP–32–51–35296A) has been installed: Accomplish paragraphs (b)(1) and (b)(2) of this AD.

(1) Within 24 hours after the last inspection performed in accordance with paragraph (a)(1) of this AD, perform a cleaning and a detailed visual inspection to detect damage (including blistering or flaking of the paint) or discoloration of the wheel hub caps and of the outer side of the inflation valve side hubs on the MLG wheels, in accordance with paragraph 2.Part B.(2) of the Accomplishment Instructions of Jetstream Service Bulletin ATP–32–48, Revision 3, dated July 15, 1994. Thereafter, prior to the first flight of each day, repeat this cleaning and inspection. The cleaning and inspection must be performed by appropriately certificated maintenance personnel as specified in section 43.3 of the Federal Aviation Regulations (14 CFR 43.3). If any

damage or discoloration is found during any inspection required by this paragraph, prior to further flight, replace the existing MLG wheel assembly and bearings with a serviceable wheel assembly and bearings, in accordance with the airplane maintenance manual.

(2) Following accomplishment of the initial inspection required by paragraph (b)(1) of this AD, once a day, perform an additional intermediate detailed visual inspection to detect damage (including blistering or flaking of the paint) or heat discoloration of the wheel hub cap and the outer side of each inflation valve side hub on the MLG wheels, in accordance with paragraph 2.Part B.(3) of the Accomplishment Instructions of Jetstream Service Bulletin ATP–32–48, Revision 3, dated July 15, 1994. The once-a-day inspections must be performed by appropriately certificated maintenance personnel, as specified in 14 CFR 43.3. If any damage or discoloration is found during any inspection required by this paragraph, prior to further flight, replace the existing MLG wheel assembly and bearings with a serviceable wheel assembly and bearings, in accordance with the airplane maintenance manual.

(c) Within 10 months after the effective date of this AD, modify the MLG, in accordance with Jetstream Service Bulletin ATP–32–51–35296A, dated May 12, 1994; and Jetstream Service Bulletin ATP–32–53–35294A (including Erratum No. 1), dated July 18, 1994, or Revision 2, dated January 13, 1995. Accomplishment of these modifications constitutes terminating action for the daily and pre-flight inspection requirements of this AD.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM–113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM–113.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) The modification shall be done in accordance with Jetstream Service Bulletin ATP–32–51–35296A, dated May 12, 1994; and Jetstream Service Bulletin ATP–32–53–35294A, dated July 18, 1994 (including Erratum No. 1), or Revision 2, dated January 13, 1995. The cleaning and inspections shall be done in accordance with Jetstream Service Bulletin ATP–32–48, Revision 1, dated January 28, 1994, or Revision 3, dated July 15, 1994. The incorporation by reference of Jetstream Service Bulletin ATP–32–48, Revision 1, dated January 28, 1994, was approved previously (including Erratum No.

1) by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51 as of March 15, 1994 (59 FR 9400, February 28, 1994). The incorporation by reference of the remainder of the service documents is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041-6029. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) This amendment becomes effective on November 29, 1995.

Issued in Renton, Washington, on October 12, 1995.

S.R. Miller,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-25835 Filed 10-27-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 95

[Docket No. 28362; Amdt. No. 392]

IFR Altitudes; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts miscellaneous amendments to the required IFR (instrument flight rules) altitudes and changeover points for certain Federal airways, jet routes, or direct routes for which a minimum or maximum en route authorized IFR altitude is prescribed. This regulatory action is needed because of changes occurring in the National Airspace System. These changes are designed to provide for the safe and efficient use of

the navigable airspace under instrument conditions in the affected areas.

EFFECTIVE DATE: 0901 UTC, November 9, 1995.

FOR FURTHER INFORMATION CONTACT: Paul J. Best, Flight Procedures Standards Branch (AFS-420), Technical Programs Division, Flight Standards Service Federal Aviation Administration, 800 Independence Avenue, SW., Washington, D.C. 20591; telephone: (202) 267-8277.

SUPPLEMENTARY INFORMATION: This amendment to part 95 of the Federal Aviation Regulations (14 CFR part 95) amends, suspends, or revokes IFR altitudes governing the operation of all aircraft in flight over a specified route or any portion of that route, as well as the changeover points (COPs) for Federal airways, jet routes, or direct routes as prescribed in part 95.

The Rule

The specified IFR altitudes, when used in conjunction with the prescribed changeover points for those routes, ensure navigation aid coverage that is adequate for safe flight operations and free of frequency interference. The reasons and circumstances that create the need for this amendment involve matters of flight safety and operational efficiency in the National Airspace System, are related to published aeronautical charts that are essential to the user, and provide for the safe and efficient use of the navigable airspace. In addition, those various reasons or circumstances require making this amendment effective before the next scheduled charting and publication date of the flight information to assure its timely availability to the user. The effective date of this amendment reflects those considerations. In view of the close and immediate relationship between these regulatory changes and

safety in air commerce, I find that notice and public procedure before adopting this amendment are impracticable and contrary to the public interest and that good cause exists for making the amendment effective in less than 30 days. The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current.

It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 95

Airspace, Navigation (air).

Issued in Washington, D.C. on October 6, 1995.

Thomas C. Accardi,
Director, Flight Standards Service.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, part 95 of the Federal Aviation Regulations (14 CFR part 95) is amended as follows:

1. The authority citation for part 95 is revised to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, and 14 CFR 11.49(b)(2).

2. Part 95 is amended to read as follows:

REVISIONS TO MINIMUM ENROUTE IFR ALTITUDES AND CHANGEOVER POINTS

[Amendment 392 Effective Date, November 9, 1995]

From	To	MEA
§ 95.1001 Direct Routes—U.S.		
22V		
Bahama Routes is amended to read in part		
Fort Lauderdale, FL VOR/DME	Dekal, FL FIX	6000
Dekal, FL FIX	Wiers, BF FIX	6000
Wiers, BF FIX	Oysta, BF FIX	10000
Oysta, BF FIX	Carey, BF FIX	6000
49V		
is amended by adding		
Dolphin, FL VORTAC	Luvly, FL FIX	2000
is amended to read in part		
Luvly, FL FIX	Junur, FL FIX	2000
54V		
Mrlin, FL FIX	Preda, FL FIX	4000
Preda, FL FIX	Isaac, BF FIX	6000